



## DO'S AND DON'TS

Follow the guidelines below for best results. MS T&T Cleaner is a biodegradable product, making it safe for a variety of applications including trucks, tractors, boats, combines and more!

### DO

- **Use 100% concentration.**
- **Use cold water** to apply foam.
- **Set your foam gun dial between 2 and 4** for best results in application.
- **Apply an even, thin layer of foam.** When application is too thick, the foam will run.
- **Allow foam to soak for about 5 minutes.**
- **Wash from the bottom up** to ensure maximum adhesion to dirt and grime.

### DON'T

- **Don't wash in direct sunlight or on hot days.** Optimal washing temperature is between 15°C and 25°C/60°F and 75°F.
- **Don't foam polished aluminum without pre-rinsing.** Use caution when washing polished surfaces.
- **Don't allow soap to dry** on vehicles and equipment. Wash in stages if this is a concern.

## PRESSURE WASHER REQUIREMENTS

- Minimum: 1100 psi
- Ideal: 1500 psi
- Maximum: 3000 psi; 6 US gallons per minute or 22 L per minute (If higher, contact your local dealer or Schippers Canada for guidance.)

**#DOYOU EVEN FOAM BRO**

**MS Schippers**  
*Passion for Farming*

**Schippers Canada Ltd.**

#120-27211 Hwy 12  
Lacombe County, AB T4L 0E3  
Phone: 1-866-995-7771  
Fax: 1-866-995-7772  
sales@schippers.ca - www.schippers.ca